

7375

CONFIDENTIAL CONTROL
OUTGOING LTR. NO.

EG&G ROCKY FLATS

90 RF 0457

DIST ET EG&G ROCKY FLATS, INC.
ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000

Althoff, F.H.	
Green, J. R.	
Burlingame, A.	XIX
Ferrera, D. N.	
Berns, L. R.	
Francis, G. E.	
Socowin, R.	
Realy, T. J.	
Baker, E. H.	
Kersh, J. M.	XX
Jrov, W. A.	
Maresca, J. R.	
McKinley, K. M.	XX
Meilen, J. B.	
Farrell, R. E.	
Sanford, T. H.	
Hannon, W. M.	
Van Leuven, D.	
Varner, B. P.	
Cund, E. R.	

January 31, 1990

90-RF-0457

Robert E. Nelson, Jr.
Manager
DOE, RFO

MONTHLY UPDATE ON STATUS OF PONDCRETE OPERATIONS

This information is for the attention of Mark Van der Puy.

Attached is a status report for pondcrete operations from December 11, 1989 through January 21, 1990. Upon your approval, please forward this report to the Colorado Department of Health. Copies are also to be provided to EPA and the Rocky Flats Environmental Monitoring Council.

If there are any questions concerning the report, please contact Vann Bynum at 966-7100 or Steve DeWitt at 966-4433.

Corres. Control	X	X
Contract Admin		
Arnold, P.	XX	XX
IGBS, F.	XX	XX
INGW, F.	XX	XX
ENR, K.	XX	XX
YNUM, V.	XX	XX
EWITT, S.	XX	XX
OTTER, G.	XX	XX
ICKLE, G.	XX	XX

[Signature]
J. M. Kersh
Associate General Manager
Environmental Restoration & Waste Management

KGP:gks

Orig. and 3 cc - R. E. Nelson, Jr.

Enclosure
As Stated

CLASSIFIER SIG.
[Signature]
-30-90
TE

Reply to Ltr. No.

3. APPROVALS.
[Signature]

1. & 2. APPROVALS.
G.P:gks

46-60 Rev. 1-80

DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

A-DU04-000312

STATUS REPORT
FOR PONDCRETE OPERATIONS
(DECEMBER 11, 1989 THROUGH JANUARY 21, 1990)

- BUILDING 788 (PROCESSING AREA)
 - One hundred sixty-eight (168) acceptable blocks of pondcrete were repackaged into eighty-four (84) plywood boxes for shipment to the Nevada Test Site (NTS)
- STORAGE PAD 750
 - Ongoing inspection of the outdoor storage pads found two blocks of pondcrete which leaked approximately five pounds of material, and one block of saltcrete which leaked less than one pound. The spills were contained and cleaned up immediately.
- STORAGE PAD 904
 - Inspection revealed one block each of pondcrete and saltcrete which each leaked approximately four pounds of material. The spills were contained and cleaned up immediately.
 - Approximately 20,000 gallons of precipitation runoff were collected by tanker truck and transported to Building 374 for evaporation.
- OTHER
 - One tent shelter has been erected on the 750 Pad, with equipment installation now in progress.

904 AND 750 PONDCRETE STORAGE AREAS
RESULTS FROM ANALYSIS OF GRAB SAMPLES

Analytical results from analysis of grab samples collected at the 750 and 904 pondcrete storage areas are summarized below. This report includes all data collected since 09/21/89. The plant guide for nitrate discharges is 10 mg/l; for gross alpha is 40 pCi/l; and for gross beta is 50 pCi/l. Also included for 750 Pad Puddle and 904 Pad Puddle are Cyanide and Cadmium results.

TABLE 1
750 PAD CULVERT

<u>SAMPLE DATE</u>	<u>NITRATE</u> <u>mg/l</u>	<u>GROSS ALPHA</u> <u>pCi/l</u>	<u>GROSS BETA</u> <u>pCi/l</u>
11/15/89	1.35	11 ± 14	10 ± 18
11/22/89	1.04	7 ± 9	6 ± 17
11/29/89	2.25	10 ± 13	17 ± 14
12/06/89	1.03	6 ± 10	12 ± 19

TABLE 2

<u>SAMPLE DATE</u>	<u>NITRATE</u> <u>mg/l</u>	<u>GROSS ALPHA</u> <u>pCi/l</u>	<u>GROSS BETA</u> <u>pCi/l</u>	<u>CYANIDE</u> <u>mg/l</u>	<u>CADMIUM</u> <u>ug/l</u>
09/21/89*	4.92	1 ± 7	14 ± 18	<0.0025	5.6
10/16/89	4.74	2 ± 9	11 ± 18	0.012	4.6
10/16/89	5.28	5 ± 11	14 ± 17	0.018	3.8
11/01/89	4.60	4 ± 9	18 ± 20	<2.5	2.2
11/29/89**	4.75	6 ± 9	20 ± 13	<0.003	4.0
12/07/89**	7.50	7 ± 11	21 ± 19	<0.003	***

TABLE 3

<u>SAMPLE DATE</u>	<u>NITRATE</u> <u>mg/l</u>	<u>GROSS ALPHA</u> <u>pCi/l</u>	<u>GROSS BETA</u> <u>pCi/l</u>	<u>CYANIDE</u> <u>mg/l</u>	<u>CADMIUM</u> <u>ug/l</u>
09/21/89*	25.1	14 ± 13	55 ± 22	<0.0025	9.2
10/16/89	5.80	10 ± 11	23 ± 19	<0.005	4.6
10/17/89	7.73	0 ± 9	27 ± 19	0.029	9.6
11/01/89	7.90	7 ± 10	9 ± 17	<2.5	6.7
11/29/89**	13.6	5 ± 9	26 ± 13	<0.004	10.2
12/07/89**	10.4	9 ± 10	25 ± 19	<0.003	***

* Previously reported but without cyanide and cadmium results

** Verbal data

*** Data to be reported in next months letter

These data were gathered as part of the routine environmental monitoring conducted by the Environmental Management group to screen runoff waters from the pads. Care must be used in any interpretation of these data, the data are derived from grab samples taken in a dynamic system.